



MOOV

Machine type
S/N
Made date
OS vision
AC power (110V/220V)
E1 camera unit
E2 camera unit /beam block
APC
APC tray
Temp. controller
Clean unit
Chuck surface check (clean)
HDD / FDD / USB
Alarm tower
Level pad
Card holder
Air Blew
Discharge Board
Touch sensor
Profile Sensor
Cover complete
VME Box
Load port
ARM1 /ARM2 /sub-chuck
Turn table
OCR
cassette cover
inspect tray
Fix tray
Cover complete
Hinge
TYPE
AC power (110V/220V)
Docking kit for
Level pad
Cover complete

UF3000	
2010-FEB	
S7.24.C8	
110	
Force	
Force	
X	
X	
Yes	ARTS-TC
Yes	15X15
ok	normal hot chuck
FD/USB	
Red / green / yellow	yes
4 set	
Force	For test type : T6372/T6373
Force	
Force	
Force	
X	
ok	
Slot1/8/107	CPU Board battery is dead

單 Load port	
Force	
Force	
TYPE6	
Force	
1 set	
1 set	
OK	
Yes	
RYEC Transmicode	
110V	
Force	For test type : T6372
2 set	
Yes	