

AMAT Endura II TiN B/S

Manufacturing Date	1/1/2020
Tool Current Status	Crated, in warehouse
Any defective or missing parts	No
Any modification/conversion/retrofit performed	No
OEM	AMAT
Tool Model	ENDURA2
Loading Configuration	3 Loadport
Retrofit Part Type 1	NA
Chamber E	Dual Mode Degas
Chamber F	Dual Mode Degas
Chamber 1	RF PVD TiN LP
Chamber 2	RF PVD TiN LP
Chamber 3	RF PVD TiN LP
Chamber 1/2/3 Chemicals/Gases Used	N2/Ar
Chamber E, F Chemicals/Gases Used	Ar
Not Sold with Tool - Description 1	NA
N2 Load Port Exists 1	No
N2 Load Port Exists 2	No
Optional Gas 1	NA