

TYPE	ORIENTATION	FLAT CUT	BACK PROCESS	THICKNESS MEASUREMENT um	RESISTIVITY	QUANTITY	IN CASSETTES
			NOTCH BP	655-698		24	
			NOTCH BP	650-698		23	
			NOTCH BP	600 RANGE		11	
EPI			LIGHT NOTCH THERMAL OX			112	YES
EPI			LIGHT NOTCH THERMAL OX			25	YES
N	1-0-0		NOTCH BP	600-620	5-20	8	
N	1-0-0		NOTCH BP	600-625	5-20	6	
N			NOTCH BP	700-790	5-20	20	
N	1-0-0		NOTCH BP	610-730	5-20	139	
N	1-0-0		NOTCH BP	666-715	.008-.023	205	
N	1-0-0		LIGHT NOTCH THERMAL OX	600-720	<1	100	
N			NOTCH	610-765	>20	67	
N			NOTCH	630-700		25	
N	1-0-0		NOTCH		1-10	67	
N	1-0-0		NOTCH	670-725	<.008	182	
N	1-0-0		NOTCH BP	680-725	<.008	250	
N	1-0-0		NOTCH	575-720	>.023	83	
N	1-0-0		NOTCH BP	695-730	.008-.023	90	
N	1-0-0		NOTCH BP	675-685	5-20	159	
N	1-0-0		NOTCH BP	690-705	5-20	237	
N	1-0-0		NOTCH BP	630-710	<.008	86	
N	1-0-0		NOTCH BP	625-730	<.008	151	
N	1-0-0		NOTCH BP	<700	>1	200	
N	1-0-0		NOTCH BP	640-700	>1	125	
N	1-0-0		NOTCH	<700	>1	135	
N, P			NOTCH BP	680-805	>20<100	70	
N, P			NOTCH	670-685		15	
N, P			NOTCH	630-670		10	
N, P			NOTCH			17	
N, P			NOTCH	600-738	>1	75	
N, P			NOTCH	630-750		260	
N, P			NOTCH	600-720	>1	275	
N, P			NOTCH CLEAR	650-670	<1	110	
N, P			LIGHT NOTCH THERMAL OX	600-720	<1	225	
N, P			LIGHT NOTCH THERMAL OX	600-720	<1	253	
N, P			NOTCH CLEAR	760-769		8	
P	1-0-0		NOTCH BP		.008-.023	50	
P			NOTCH	670-680		25	
P			NOTCH BP	600-650	5-20	25	
P	1-0-0		NOTCH BP		5-20	25	
P	1-0-0		NOTCH BP		.008-.023	2	
P	1-0-0		NOTCH BP		5-20	13	
P	1-0-0		NOTCH BP	685-690	5-20	166	
P	1-0-0		NOTCH BP	700-735	5-20	230	
P	1-0-0		NOTCH	665-720	.008-.023	57	

P	1-0-0	NOTCH CLEAR	600-720	>1	250	
P	1-0-0	NOTCH	600-700	10-20	31	
P		NOTCH	600-670	1-10	10	
P	1-0-0	NOTCH	600-730	5-20	105	
P	1-0-0	NOTCH	605-810	5-20	175	
P	1-0-0	NOTCH	610-720	>20<100	226	
P		NOTCH BP	648-690	10-30	55	
P	1-0-0	NOTCH BP	690-710	>20<100	233	
P	1-0-0	NOTCH BP			40	
P	1-0-0	NOTCH BP	680-685	5-20	95	
P	1-0-0	NOTCH BP	700-775	.008-.023	194	
P	1-0-0	NOTCH BP	625-660	.008-.023	6	
P	1-0-0	NOTCH BP	575-665	.008-.023	235	
P	1-0-0	NOTCH BP	<700	>1	170	
P	1-0-0	NOTCH BP	585-680	<.008	235	
P	1-0-0	NOTCH BP	628-718	>1	254	
P	1-0-0	NOTCH BP	680-705	<.008	246	
P	1-0-0	NOTCH BP	705-730	<.008	150	
P	1-0-0	NOTCH BP	540-665	5-20	263	
P	1-0-0	NOTCH BP	660-675	5-20	260	
P	1-0-0	NOTCH BP	690-700	5-20	248	
P	1-0-0	NOTCH BP	695-705	5-2-	214	
P, POLISHED, W/PAT		NOTCH BP	647-687		8	
P, POLISHED, W/PAT		NOTCH BP	700-725	5-20	235	
		LIGHT				
	1-0-0	NOTCH THERMAL OX	742-744		13	YES
		LIGHT				
		NOTCH THERMAL OX			9	YES
		NOTCH DSP			2	
		NOTCH CLEAR		.005-.02	4	
		LIGHT				
		NOTCH THERMAL OX		.008-.03	24	YES
		NOTCH BP	600-625	5-20	7	
		NOTCH BP			14	
		NOTCH BP	600-625		4	
		NOTCH BP		.008-.03	9	
		LIGHT				
		THERMAL OX			3	YES
		LIGHT				
		THERMAL OX			25	YES
		LIGHT				
		THERMAL OX			25	YES
		CLEAR		659-663	2	YES
		LIGHT				
		THERMAL OX		700-750	9	YES
		LIGHT				
		THERMAL OX			18	YES

	LIGHT			
	THERMAL	25		YES
	OX			
	LIGHT			
	THERMAL	6		YES
	OX			
	LIGHT			
NOTCH	THERMAL	200		
	OX			
	LIGHT			
NOTCH	THERMAL	194		
	OX			
NOTCH				
	LIGHT			
NOTCH	THERMAL	22		
	OX			
NOTCH		60		
NOTCH		57		
	LIGHT			
NOTCH	THERMAL	701		
	OX			
	LIGHT			
NOTCH	THERMAL	467		
	OX			
NOTCH	DSP	205		
	LIGHT			
NOTCH	THERMAL	349		
	OX			
NOTCH		18		
NOTCH	BP	34		
NOTCH	BP	28		
	LIGHT			
NOTCH	THERMAL	64		
	OX			
NOTCH	BP	43		
NOTCH	BP	62		
NOTCH	BP	675-735	<5>.023	130
NOTCH	BP	670-672		13