



## SemiTool conditions

### PARTS BROKEN OR MISSED:

- ATMI SILICON PASTE KIT
- O-RING 6 MM X 2 MM
- O-RING 6 MM X2 MM EPDM
- LAMP REPLACEMENT PHOTOSPEC ANALYZER
- AMPLIFIER MOTOR DIGIFLEX
- VALVE BLOCK TANK 2
- V-BAND ASSEMBLY, CFDIII 200MM (CLAMPCO)
- BRD ASSY LINE DRIVER (FOR 61525-02)
- ROTOR ASM PLTNG 100A BELWS HG N2 200M
- BPS-3.6/CONTROLLER/PLC MODULE
- MOTOR SCHEMATIC DRIVEHEAD ASM
- CP6 spin motor
- CP5 : spin amplifier
- CP3: Levitronix PUMP DANNEGGIATA
- Controler and PLC PRELEVATI for CP4 .
- CP4/CP8 /CP2 : fails of motor amplifier
- TR / PR Robot (paddle missed)
- TR robot controller
- CP4 Levitronix pump and plating power supply
  
- CP7 :
  - ✓ Rotor
  - ✓ Shield weir
  - ✓ Spin driver card
  - ✓ CPC flow
  - ✓ CP8 levitronix pump
  
- Tank 2 PUMP
- Tank3 PUMP
  
- Main PC broken