



MOOV

Missing parts as below:

No .	Chamber A	Chamber B	Chamber D	Mainframe	Loadlock	AC rack
1	Platen assy	Shower head	Throttle valve	OTF sensor	manometer	IO board
2	heater assy	Throttle valve	Iso Valve	Robot faulty	cassette assy	Unable to power on
3	Throttle valve	Platen assy motor	Platen assy motor	Robot arm	mapping board	
4	RFG-2000 generator	Slit door cylinder	Motor driver board			
5	Slit door cylinder	Process kit	Process kit			
6	Chamber manometer					
7	Motor driver board					
8	Process kit					